

Release Note

Release Date: September 2020

Product Ver.: Civil 2020 (v3.2)



DESIGN OF CIVIL STRUCTURES

Enhancements

- 1. Improvement of Bridge Assessment to CS 454: Crack Width of External/Unbonded Prestressing
- 2. Improvement of Bridge Assessment to CS 454: Torsional Reserve Factor Results
- 3. Improvement of Prestressed Girder Design to BS 5400: Longitudinal Shear
- 4. AASHTO LRFD 8th Design Standard Steel Section
- 5. Warping Normal Stress for Steel Composite Section Design to AASHTO LRFD
- 6. Bug fix list





Civil 2020

1. Improvement of Bridge Assessment to CS 454: Crack Width of External/Unbonded Prestressing

• For the crack width calculation, prestressed structures containing external and/or unbonded prestressing must be treated as reinforced concrete sections in which the axial force and moment due to prestress is considered as an applied load. Axial force was not taken into account in the previous version. Now, crack width is calculated considering axial force as well as moment.

Rating > Bridge Rating Design > CS 454/19





Crack width calculation report

2. Improvement of Bridge Assessment to CS 454: Torsional Reserve Factor Results

• The method to determine Adequacy factor for torsion is improved as shown below.

■ Rating > Bridge Rating Design > CS 454/19

	Element	Part	Rating Case	vt (kN/m²)	vtmin (kN/m²)	v (kN/m²)	vtu (kN/m²)	y1 (m)	vtu(y1/550) (kN/m²)	T (kN·m)	Tu (kN·m)	А	Che
	1	[[1]	ULS_Mxx(Max)	665.4657	473.4272	-2866.011	6480.0000	4.8355	-	7080.6312	9477.6888	1.338	ОК
	1	[[1]	ULS_Mxx(Min)	665.4657	473.4272	-2866.011	6480.0000	4.8355	-	-7080.631	9477.6888	1.338	ОК
	1	[[1]	ULS_Myy(Max)	43.8766	473.4272	-	-	4.8355	-	-	-	10.79	ОК
	1	[[1]	ULS_Myy(Min)	0.0047	473.4272	-	-	4.8355	-	-	-	1015	ОК
	1	[[1]	ULS_Mzz(Max)	559.3364	473.4272	-2869.134	6480.0000	4.8355	-	5951.4037	9477.6888	1.592	ОК
	1	[[1]	ULS_Mzz(Min)	559.3367	473.4272	-2869.133	6480.0000	4.8355	-	-5951.406	9477.6888	1.592	ОК
	1	J[2]	ULS_Fxx(Max)	190.4501	473.4272	-	-	4.8355	-	-	-	2.485	ОК
	1	J[2]	ULS_Fxx(Min)	0.0047	473.4272	-	-	4.8355	-	-	-	1014	ОК
	1	J[2]	ULS_Fyy(Max)	217.6501	473.4272	-	-	4.8355	-	-	-	2.175	ОК
	1	J[2]	ULS_Fyy(Min)	221.8854	473.4272	-	-	4.8355	-	-	-	2.133	ОК
	1	J[2]	ULS_Fzz(Max)	1.3240	473.4272	-	-	4.8355	-	-	-	357.5	ОК
	1	J[2]	ULS_Fzz(Min)	248.9830	473.4272	-	-	4.8355	-	-	-	1.901	ОК
	1	J[2]	ULS_Mxx(Max)	623.2512	473.4272	-2147.980	6480.0000	4.8355	-	6631.4638	9477.6888	1.429	ОК
	1	J[2]	ULS_Mxx(Min)	623.2512	473.4272	-2259.093	6480.0000	4.8355	-	-6631.463	9477.6888	1.429	ОК
	1	J[2]	ULS_Myy(Max)	190.4501	473.4272	-	-	4.8355	-	-	-	2.485	ОК
	1	J[2]	ULS_Myy(Min)	0.0047	473.4272	-	-	4.8355	-	-	-	1014	ОК
	1	J[2]	ULS_Mzz(Max)	614.1632	473.4272	-2122.454	6480.0000	4.8355	-	6534.7661	9477.6888	1.450	ОК
	1	J[2]	ULS_Mzz(Min)	615.2203	473.4272	-2278.913	6480.0000	4.8355	-	-6546.014	9477.6888		
	2	[2]	ULS_Fxx(Max)	206.8457	473.4272	-	-	4.8355	-	-	-		
	2	[2]	ULS_Fxx(Min)	1.3264	473.4272	-	-	4.8355	-	-	-	1	
	2	I[2]	ULS Fyy(Max)	217.6500	473.4272	-	-	4.8355	-	-	-	1	
4 ►	Torsion	Reserv	e Factors /						<				

Adequacy Factor, A

If $v_t \leq v_{tmin}$,

 $A = v_{tmin}/v_t$

If $v_t > v_{tmin}$,

 $A_1 = v_{tu}/(v + v_t)$

 $A_2 = T_u/T$

 $A = \min(A_1, A_2)$

Torsion Reserve Factor Table







3. Improvement of Prestressed Girder Design to BS 5400: Longitudinal Shear


• Longitudinal shear force per unit length of a composite member is calculated at the interface of the precast unit and the in situ concrete.







Potential shear plane	Longitudinal shear check
1-1	Supported
2-2	Not supported
2'-2'	Not supported



Longitudinal Shear Check Report




4. AASHTO LRFD 8th Design Standard – Steel Section

- New AASHTO LRFD design standard can be applied to steel design. New type of report is provided.
- Steel Section (H or I section, box section (HSS), circular pipe (HSS), T or double angle, channel, single angle, rectangular bar, solid round)







■ Member Design Detail Report AASHTO-LRFD 2017

1. Member Information

· Member: 4

2. Material (1) Material Name : A36 (2) F_y : 36.00ksi (3) E_s : 29,000ksi

3 Length

s. Lengtn	
(1) L _v	: 10.00ft
(2) L _z	: 10.00ft
(3) L _b	: 10.00ft
(4) K _v	: 1.000
(5) K _z	: 1.000



4. Section

(1) Shape : W16x67 (Rolled)

(2) Section Property

.,				
As	A _{sy}	A _{sz}	Y _{bar}	Z _{bar}
19.70in²	11.34in²	6.450in²	5.117in	8.165in
Sy	Sz	Z _y	Zz	J
117in³	23.20in³	130in³	35.50in³	2.390in ⁴
r _y	rz	ly	Iz	l _{yz}
6.960in	2.460in	954in³	119in³	0.000in4

5. Check Axial Strength

Category	Value	Criteria	Ratio	Note
Slenderness Ratio	48.78	120	0.407	
Compression Strength (kip)	0.710	594	0.00120	
Slenderness Ratio		0.41		

Word Format Design Report

Design Result Table




Civil 2020

5. Warping Normal Stress for Steel Composite Section Design to AASHTO LRFD

- Normal stress due to restrained warping can be introduced in the design of steel composite section to AASHTO LRFD 17.
- 7th dof option from the Section dialog box and warping normal stress option from the Design Parameter dialog box should be checked on.

Design > Composite Design > AASHTO LRFD 17



$$\sigma_{xx} = \frac{N}{A} + \frac{M_y}{I_y} z - \frac{M_z}{I_z} y + \frac{B}{C_w} \psi \qquad \begin{array}{l} \text{B: Bi-moment} \\ \Psi \text{: Warping function} \\ \text{C}_w \text{: Warping constant} \end{array}$$

A					F																		Ζ	AA	AB	ΑC
480	•	Second-order elastic compression-flange L									l ber	nding	stress	(AAS	нто	LRFD	Bridg	ge, 2	017,	6.10	.1.6)					
481	i. Because of discretely braced flange.									(for curved bridge)																
482		fı	_ M _{uz} _ 216.056				6	_			1 04	4 ksi														
483		11 = S ₁		Sı				3			1.04	4 K3I														
484	_									_																
485		Because of torsional warping																								
486		f _{Lw} = M _b ·		_b -w =			-0.145 ks																			
487		I,w - I _w					0.170 No.																			
488		in which :																								
489		M_b	:	Bi-m	noment																					
490		l _w	: Warping constant																							
491		w : Warping function at stress							point																	
492																										
505	① Check flange nominal yielding																									
506		f _{bu}	+ f _l	=	-1	1.619		≤		Φ_{f}	- R _h	F _{yc}	=		68.89	95 ksi									0	K
507		$f_{bu} + f_{I} = -11.619$ in which :																								
508			Ф	=		1.000																				
509			R _h	=		0.984																				
510																										
511	(2) Che	ck fle	exura	l resista	nce																				
512		f _b	ս + f	+ f _i /3 = -10.80		305		≤		Φ_{f}	· F _{nc}	=		54.06	50 ksi									0	K	
513		in w	hich	nich :																						
514			Ф	=		1.000																				
515			Fnc	=		54.060) ksi																			

Design Report

6. Bug fix list

- 1. [Tendon re-tension] For the re-tension of tendon, relaxation losses are incorrectly calculated. When one tendon among multiple cables in a beam is re-tensioned, stresses in the other tendons are displayed as zero in the Tendon Loss table.
- 2. While using the standard vehicle from AS5100.2- Heavy Load Platform (Both HLP320 PR HLP400), program gives this error: "ERROR IN READ MODEL DATA: R_MOVE_AUST"
- 3. Analysis stopped with the error message below when the model included 7 dof of composite section, nonlinear point spring support and moving load analysis.

[WARNING] DISK SPACE IS NOT SUFFICIENT OR FILE ACCESS IS NOT ALLOWED BY ANTIVIRUS. PLEASE, CHECK DISK SPACE OR ANTIVIRUS PROGRAM OPTIONS

ERRORS ENCOUNTERED. MIDAS JOB TERMINATED. REFER TO .OUT FILE

- 4. Analysis stopped while moving load optimization was performed for the BD 37/01.
- 5. [Moving Load Analysis to Eurocode]
- Tracer Results were not matching with moving load analysis results. This was happening when there were two moving load cases with railway vehicles, one with Dynamic Allowance Factor and another without Dynamic Allowance Factor.
- Incorrect centrifugal forces from moving load tracer for the LM 71 train load. This was happening
 when the lanes were defined with the 'Lane Element' method.

6. Bug fix list

6. Analysis stopped with the following error message when point spring supports were used in the construction stage Non-linear analysis. This was happening when some components of point spring supports were fixed.

Spring Element Property is not Proper.

- 7. [Moving load analysis to CS 454]
 - While performing moving load optimization with ALL Model 1, the uniformly distributed load was
 not applied in the remaining area. Even in this release, the moving load optimization function does
 not take into account the remaining area for UDL which needs to be defined separately by the
 user.
 - When performing moving load optimization, the Moving Load Tracer crashed when trying to view the results for two different load cases at the time of the second load case.
 - When performing moving load optimization for the combined ALL Model 2 and SV 196, SV 196
 was not applied when the lane width was smaller than 2.65 m which corresponded to vehicle
 width.
 - The difference in the results between Moving Load Tracer and converted static loads for the combined ALL Model 2 and HB: This was happening when HB load was defined using user-defined vehicle and the unit of HB was other than 30.
- 8. [Moving load analysis to Polish code] When there were more than one moving load case for optimization, the results of the second moving load case were wrong.
- 9. [Beam Section Temperature] The analysis results were wrong when Beam Section Temperature load was applied to Composite PSC section (Composite-I, Composite-T, Composite-PSC).

6. Bug fix list

- 10. [Inelastic time history analysis]
- Initial axial force of PM Multi-Curve hinge was not properly saved and thus the associated hinge reached failure status unexpectedly.
- Time history analysis was running very slow. The analysis was stuck at 13% and not moving ahead.

11. [GSD]

- The area of rebars shown on the corner of bottom-right side was incorrect for a huge section.
- Yield moment at axial force = 0 was shown as zero when hinge property was imported from midas GSD.
 This was happening when moment-curvature calculation was not converged for a very large size of section.
- 12. [Steel Composite Girder Design to Eurocode] When trying to define longitudinal stiffeners for the composite-general section, the program gives the following error message.

Can't Find DgnBaseManager.dgne